



*heating and plumbing products  
that won't cost the **earth***

## Using solar trade tools

January 2010



# Using solar trade tools

Making pipe connections to stainless steel solar pipe is an easy process when you use our Inta Inox pipe cutter and flanging tools. Here's how.



1

Cut solar pipe to length with an Inta Inox pipe cutter. Do not use a hacksaw.



2

Place the nut on the pipe and then clamp the bar leaving 3 ridges of pipe above the jaws.



Inta Inox pipe cutter



3

Centre the flange forming tool and angle it to grip the clamp.



4

Compress the pipe by winding down the handwheel. Use the ratchet action to tighten until flat. The flange is now formed.



Inta Inox flanging tool



5

Look for an even and flat surface to the newly made flange.




6

Now place a "C" clip behind the flange. This ensures that the brass union nut does not damage the flange on tightening.



female thread with c clip & gasket



7

Tighten the fitting to form the solar pipe connection.



8